DropQuant Release notes

Software product	DropQuant
Version	1.5.0
Changes listed are in regard to version	1.4.1

Bug fixes

- Export of Standard curve graph is incorrect
- Multiple IQOQ export layout errors
- Oligo import sequence does not allow degenerate base symbols (R,Y,K,...)
- Wavelength calibration freezes during calculation
- Plate layout export in Excel 2013 overlays sheet1 and sheet2
- "Last calibration date" is not updated after Wavelength calibration for administrators

Improvements

- Change website registration link at install time to new website
- Disable standard 96 well plates for new instruments (rev v1.3 or higher)

New Features

- Added "Wavelength Calibration" option for administrator level
- Added nm to Wavelength calibration report for administrators